

## Üç Fazlı Yarımlı Kalıp Sarım Şeması

X=36 Oyuk

2p=2 Kutup

m=3 Faz

C=6

$\alpha^\circ=10^\circ$

$y_1=1-14$

$y_2=1-16$

$y_3=1-18$

### Formüller

$$C = \frac{X}{2p \cdot m} = \frac{36}{2 \cdot 3} = 6 \quad \alpha^\circ = \frac{360 \cdot P}{X} = \frac{360 \cdot 1}{36} = 10^\circ \quad y = \frac{X}{2p} = \frac{36}{2} = 18$$

